


Release Notes Cathexis Vision 2014 Service Pack 3

027-20140826-05 Rev 1.3 September 11, 2014 MN Brecher

Contents

1	Critical	2
	Major	
	Normal	
	Minor	
	Informational	



(fix)

(addition)

Note:

- I. While Cathexis has made every effort to ensure the accuracy of this document, there is no guarantee of accuracy, neither explicit, nor implied. Specifications are subject to change without notice.
- II. Further information on cameras listed in these Change Notes should be sought here: http://integrations.cathexisvideo.com/supported-i-p-cameras/
- III. Further information on integrated devices listed in these Change Notes should be sought here: http://www.cathexisintegrations.com/supported-integrations/

1 Critical

#	Severity	Туре	Software Change	Key area
1	1	Problem	Please note that PostgreSQL will no longer be officially supported on NetBSD 3 from CathexisVision 2014 SP3. This means that a NetBSD 3 system will not be able to operate as an alarm gateway system.	Gateway

2 Major

#	Severity	Туре	Software Change	Key area
1.		Feature	WBX weighbridge integration. This integration device is designed to receive data sent from the WBX weighbridge service. It receives: 1. Heartbeat messages, which indicate the connection is up. 2. Transaction messages which contained data sent from a particular weighbridge.	Integration
2.		Feature	Samsung SUNAPI 2.0 camera integration added.	Network devices
3.		Modification	Improved live video when an NTSC camera is used on a PAL system.	User interface
4.		Modification	Remove old maintenance licenses and report on new camera maintenance licenses. CathexisVision2015 will use a camera based maintenance license model (instead of server based). This change allows CathexisVision2014 to report on what camera maintenance licenses will be needed if the site is upgraded to CathexisVision 2015.	Licensing
5.	<u> </u>	Modification	Increase UDP receive buffer size for integrations that use a UDP channel. This is to fix a problem where some transactions might be lost.	Integration
6.		Modification	Place limits on the number of simultaneous streams served to mobile devices/web browsers. 1. For NetBSD based recorders:	Mobile
7.		Modification	Improved the scheduling of VOM15 compressions, on heavily loaded systems. Improved the scheduling of VOM15 compressions on heavily loaded systems to compensate for vastly different request rates which might be experienced when low frame rate recording and high frame rate remote live streaming are done on different cameras. This will be of most relevance to old single core NetBSD 3 systems.	Frame grabbers

8.	Problem	Surveon CAM2321 problem.	Network devices
		Fixed a problem that was causing video corruption on the Surveon CAM2321 camera.	
9.	Problem	Disk error technical alarm dialout frequency.	Alarms
		Fixed a problem where technical alarms generated by SMART disk errors were repeating every 5 minutes even though the technical alarm was configured to repeat every 12 hours.	
10.	Problem	Fixed issue with alarm for advanced database errors not being sent.	Database
10.	Problem	Fixed an iterator problem on Windows which causes problem with ONVIF.	Network devices
		This compile problem was evident on windows only.	
11.	Problem	Event messages on some newer Pelco camera models were not sent through.	Network devices
12.	Problem	 Samsung V2 driver problem fixes. Analytics triggers did not come through. CathexisVision got information about a different 	Network devices
	D. dalam	stream on the camera to the one expected. Fixed HTMLServer crash on slow systems viewing high	Na de la la
13.	Problem	bitrate cameras.	Mobile
14.	Problem	Fixed a crash which can happen when logging out while streaming video with a mobile device or a web client.	Mobile
15.	Problem	Fix archive file verification from GUI on Windows NVR.	Archiving
16.	Problem	Fixed an issue with RTSP authentication which meant an IP camera would not stream.	Network devices
17.	Problem	Fixed web/mobile live streaming issues.	Mobile
18.	Problem	Flir camera problem. The NVR would crash, when the camera could not be pinged.	Network devices
19.	Problem	Fixed a problem with the performance monitor, on large sites.	Profiling
20.	Problem	Fixed a problem that caused the SAM3101 to reboot, when entering and exiting configuration.	Alarms
21.	Problem	Saflec problem. Causing the integration server to crash.	Integration

22.	<u> </u>	Problem	Flexwatch fix. Fixed two issues on Flexwatch cameras: 1. Cameras less than 2MP were not presenting the correct video capabilities. 2. Camera would not stop `zooming.	Network devices
23.		Problem	JVC VN-H fixes. The following three issues were fixed: 1. Multicast did not stream. 2. Could not playback audio. 3. Poor video quality and frame rate.	Network devices

3 Normal

#	Severity:	Туре	Software Change	Key area
1	<u>Q</u>	Feature	Genesis wireless PIR. Requires the FEATURE_CATHEXISVISION_GENESIS license. Features 1. The software connects to a genesis masterhead. 2. The masterhead is able to connect to a maximum of 32 PIR detectors, and relay if the PIR is trigged (set off). 3. The masterhead is also able to send the battery status of the PIR, if the data is received through a walk test unit.	Integration
2	Ą	Feature	Hunt camera feature addition. Add the Hunt "video loss trigger". When the video source goes down, the "STARTVIDEOLOSS" trigger will be sent to the system.	Network devices
3	Ą	Feature	Added the Sunell Camera drivers.	Network devices
4	Ą	Feature	Added I/O to Surveon driver.	Network devices

5		Feature	Repos POS integration. The following licenses are required: 1. FEATURE_CATHEXISVISION_POS 2. FEATURE_CATHEXISVISION_POS_TILL 3. FEATURE_CATHEXISVISION_POS_TILL_UNLIMI TED The driver is able to connect to multiple tills. The driver connects to each till on a separate serial COM port. Each till is identified based on the COM port it is connected to. Repos POS features. 1. Connect to multiple tills on separate serial ports. 2. Each till is associated with a till object 3. Receives live transactions from each till, and displays them as transaction event messages. 4. This device has a POS interface. This enables viewing of a camera associated with a till object, and live transactions in the same window. 5. Each transaction event is stored in a metabase.	Integration
6	Ą	Feature	Hitron and Hitron Legacy driver. 1. Added a Hitron legacy driver. 2. Added support for the Hitron NFX-12053B1 camera.	Network devices
7	A	Feature	UDP Technology driver added.	Network devices

8	P	Feature	Paxton access control integration.	Integration
			The following licenses are required: FEATURE_CATHEXISVISION_ACCESS FEATURE_CATHEXISVISION_ACCESS_DOOR or FEATURE_CATHEXISVISION_ACCESS_DOOR_UNLIMITE D This device accepts a TCP connection from the Paxton wrapper, and is able to receive a list of doors and access events per door from the Paxton access control system.	
			 Connects to the Paxton system, and receives a list of doors currently added to the system. Access events are received for each door in the Paxton system. Access events are stored in a metadb. The user can filter on event types and event subtypes in the metadb. 	
9	Ą	Feature	Added support for toggle buttons in the PTZ control panel, and enabled them for control of the Intervid PTZ.	User interface
10	Ø	Feature	ZKTeco camera driver added.	Network devices
11	Ą	Feature	Fixed Linux restore point permissions issues, and remote rp management. 1. Fixed permissions problems when managing configuration backups with non-root users on Linux. 2. Implemented remote configuration backup management.	Configuration
12	Ą	Feature	Added the FLIR integration. Licenses: This requires two CLIC-2000 licenses - one for the daylight camera and the other for the infrared camera.	Network devices
13	Ą	Feature	Added zoom to area to Hikvision.	Network devices
14	Ą	Feature	Hitron HDG-T320(NSRS7) driver added.	Network devices
15	Q	Feature	Vista VK2-1080XVRPTZ camera drivers added.	Network devices

16	P P	Feature	Added support for the Hikvision DS-2CD6332FWD-IV, fisheye camera. 1. Supports 5 video inputs (1st being the fisheye view with the rest being transforms). 2. PTZ can be used for the transformed views. 3. Multicast will only stream to port 8860.	Network devices Integration
	Ą	Modification	 Modified the FlexWATCH driver to conform to new API information. This change allows us to more accurately represent resolutions and framerates. We now also support multicast and enabling of audio from within our setup. 	incegration
18	A	Modification	Increase max live video decoders from 8 to 12.	Streaming video
19	Ą	Modification	Minor licensing changes. 1. Email event action moved from Pro to Core. 2. Site map license moved from Core to Lite.	Licensing
20	Ą	Modification	Support added for CathexisVision 2015 and later camera licenses.	licensing
21	Ą	Modification	Adjusted the Impro IXP20 driver name to reflect compatibility with APLITE. Driver is now named IXP20 / APLITE access control.	integration
22	Ą	Modification	Modified the Softcon driver to make I/O state changes compatible with maps. Any changes to the I/O states can now be viewed on maps.	Integration
23	Ą	Problem	Ignore TeamViewer VPN Adapter as dongle on Windows. TeamViewer masquerades as an Ethernet adapter, and this incorrectly contributed to the calculation of the license information. TeamViewer IDs are now excluded.	Licensing
24	P	Problem	Fixed a problem that prevented access to serial ports above com9.	Communications
25	Ą	Problem	Added support for archiving from PostgreSQL gateway database.	Archiving
26	A	Problem	Added firewall exceptions for performance monitors, on Windows.	Profiling
27	Ą	Problem	Technoswitch tec202 fire panel. Fixed a problem where CathexisVision was unable to communicate with multiple panels.	Integration

28	Ŋ	Problem	Modified the Softcon driver to process reader events faster. Fixed a problem that caused reader events to populate the database slowly.	Integration
29	A	Problem	Prevent de-interlacing of images that are not exactly 704 or 720 wide.	Core
30	Ą	Problem	 Modified support for 3MP Hunt cameras. Set max frame rate to 20fps. Corrected the video input resolution parameter, so that resolutions will be adjusted correctly. 	Network devices
31	Ą	Problem	Fixed Ubuntu archive viewer authenticity verification.	Archiving
32	A	Problem	Fixed a problem that caused a crash when adding a Pelco camera.	Network devices
33	Ą	Problem	Fixed a random html server crash.	Mobile
34	Ą	Problem	Fixed issue where restoring a configuration backup would, occasionally, not work on Windows.	Configuration
35	Ą	Problem	Surveon CAM6181 support added.	Network devices
36	Ą	Problem	Surveon CAM3371. 1. Removed multicast option. 2. Fix setup of 1280x960 resolution.	Network devices
37	A	Problem	Fix Vivotek serial port setup. Could not set serial port to even parity.	Network devices
38	Ą	Problem	 Map editor. Fixed the 'Set Icon' animation action. Improved icon management in the map editor. 	User interface
39	Ą	Problem	Removed MPEG4 option on Surveon CAM2511.	Network devices
40	Ą	Problem	Fixed the Hikvision DS-2CD2012-I integration. 1. JPEG quality would not change. 2. Multicast would not stream.	Network devices
41	Ą	Problem	Fix opening of gateway case attachments on Ubuntu. This was not supported on Ubuntu. This has been corrected.	User interface

42	Ą	Problem	 Samsung camera changes. The Samsung Legacy driver is now available. It is called "Samsung Legacy". The current "Samsung" driver has been renamed to "Samsung V1". The control port on the Samsung legacy drivers has been set to port 4000, which is the default port. Note: The camera will not stream video if the control port on the camera does not match up to port 4000. 	Network devices
43	Ą	Problem	Bosch H263 AVI conversion problem fix. Fixed the Bosch H263 AVI archive conversion.	Archiving
44	B	Problem	Impro IXP20 problem. Some events would not come through.	Integration
45	Ą	Problem	Fedora audio fix. Fixed a problem in the Fedora software that meant that non-root users could not listen to audio.	Audio
46	Ą	Problem	Canon. Made the following changes: Made the following changes in the Canon stream setup: 1. Fixed setup of the VB-S900F. 2. Added audio support. 3. Added multicast support.	Network devices
47	À	Problem	 Removed I/O, as it is not in the driver. Fixed Triggers not appearing in the Trigger History. Fixed Event Triggers not coming through. 	Network devices
48	Ą	Problem	Remove upgrade process from HDE watchdog list. Fixed a problem where the upgrade fails after uploading 1-2%.	Network devices
49	Ą	Problem	Fix loading of polygons with 3 points. Fixed a problem that caused three sided polygons to not be loaded when viewing the map.	User interface
50	Ą	Problem	Fix Alsa audio playback on Ubuntu. Fixed a crash that occurred when trying to playback audio in Ubuntu.	Audio

4 Minor

#	Severity:	Туре	Software Change	Key area
1		Modification	Added camera information to Surveon driver. The Surveon driver will now display the model, firmware version, serial number and MAC address.	Network devices
2	H	Modification	Disallow recording trigger camera from "any device" event triggers. The recording of trigger cameras is not supported, but it was still offered, this removes it from the menu.	Integration
3	8	Modification	Removed the "open CD/USB drive" buttons, in Ubuntu archive viewer, as they are not required.	Archiving
4	3	Modification	Hide notification field on Impro IXP20 / Access Portal. This is now hidden, as it is obsolete.	Integration
5		Modification	Fixed a problem that kept the previous versions of Start Menu shortcuts after an upgrade.	Production
6		Problem	Scheduled gateway report problem. Fixed a problem that was causing mail is sent repeatedly to the first recipient, if the email recipients, for scheduled gateway reports, were separated with a ';'.	Gateway
7		Problem	CatMap fix. Prevent rotation of camera zones with camera icon rotation on the map.	User interface

5 Informational

#	Severity:	Туре	Software Change	Key area
1	&	Modification	Include advanced database slice location, in alert messages. Include the advanced database slice location in the alert message that appears in the database setup alerts section, when a slice has a problem.	Database
2	2 .	Problem	Ubuntu/Fedora problem fix This change allowed site reports to be exported to disk on Ubuntu.	User interface